


TIC



SMUD

SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

March 28, 1980



Mr. R. H. Engelken, Director
Region V
Nuclear Regulatory Commission
1990 North California Boulevard
Suite 202, Walnut Creek Plaza
Walnut Creek, Ca. 94596

Docket No.: 50-312
Re: IE Bulletin 79-17, Revision 1
Pipe Cracks in Stagnant Borated Water Systems
at PWR Plants

Dear Mr. Engelken:

Examinations were performed at Rancho Seco in accordance with Item 2b of IE Bulletin 79-17 with no reportable indications noted. Three recordable indications were noted in two welds (two in one weld and one in another weld), which were all determined to be geometric reflections caused by weld root configuration or counterbore.

We consider our response to the requirements of IE Bulletin 79-17, Revision 1, complete. If you have any questions, please contact Mr. Ron Colombo of my staff.

Respectfully Submitted,

J. J. Mattimoe
J. J. Mattimoe,
Chief Engineer

cc: Office of Inspection & Enforcement