

Appendix A

NOTICE OF VIOLATION

Toledo Edison Company

Docket No. 50-346

Based on the inspection conducted on April 8-11, 15-25, 29-30, May 1, 2, 5-9, 1980, it appears that certain of your activities were in noncompliance with NRC requirements as noted below. This item is a noncompliance of the deficiency level.

Technical Specification 3.3.3.8 requires the fire detection instrumentation to be operable at all times, or to establish within one hour a fire watch patrol.

Contrary to the above on April 17, 1980, power was lost to the fire detection instrumentation at 1400 hours and a fire watch patrol was not established until approximately 1700 hours.

8007210325