



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

January 29, 1979

Docket No. 50-346

71  
CRESWELL  
DAVIS BESSE  
SEPT 24, 1971

MEMORANDUM FOR: J. F. Streater, Chief, Nuclear Support Section  
FROM: J. S. Creswell, Reactor Inspector  
SUBJECT: TECHNICAL EVALUATIONS AT DAVIS-BESSE 1  
REFERENCE: MEMORANDUM FROM J. F. STREETER TO J. S. CRESWELL,  
DID, DECEMBER 10, 1978

In response to your memo I am furnishing the requested information:

1. Loss of Pressurizer Level Indication

A. Identified in IE reports:

50-346/78-06, paragraphs 1 and 9a and c  
50-346/78-17, paragraph 5 (FCR 77-515)  
50-346/78-27, paragraph 8  
50-346/78-30, paragraph 1 (unresolved item 346/78-13)  
paragraph 4

2. Replacement Valves for Incore Detector String H-8

A. Identified in IE reports:

50-346/78-17, paragraph 6 and 9 - Notice of Violation  
50-346/78-30, paragraph 2 - Noncompliance (346/78-16)

3. Rod Drop Testing

A. Identified in IE reports:

50-346/78-06, paragraph 6  
50-346/78-17, paragraphs 8, 9 and 13

4. Al Moore Memo - Preoperational Testing

A. Identified in IE report:

50-346/78-17, paragraph 4

POOR ORIGINAL

8001160 931 Q

January 29, 1979

## 5. CNRS Review of Startup Test Results

## A. Identified in IE reports:

50-346/78-17, paragraph 2

50-346/78-30, paragraph 2 (noncompliance 346/78-15)

## 6. Motorizing of Generator

## A. Identified in IE report 50-346/78-17, paragraph 5

## 7. FCR for Bus Stripping

## A. Identified in IE report 50-346/78-17, paragraph 5 (FCR 78-049)

On August 16, 1978 a management meeting was held with the licensee. During that meeting it is my understanding the following items were discussed regarding the quality and timeliness of reviews. Examples of things being accepted at face value were:

- (1) Replacement valves for incore detector H-8
- (2) G.E. memo on turbine motorizing
- (3) Al Moore Memo
- (4) Inadequacies in SFAS test
- (5) Failure of SNRS to review S/U Test results and audits
- (6) FCR for stripping buses.

Making reviews in a timely manner was also addressed:

1. G.E. memo on motorizing the generator should have received critical evaluations.
2. Al Moore memo was of real significance and this was not realized.
3. SFAS deficiency went through many reviews in the test program.
4. CNRS failure to review S/U test results.

It is my understanding that the licensee was aware of these problems.

POOR ORIGINAL

January 29, 1979

Since this meeting took place the following issues have been addressed:

1. High pressure injection performance during September 24, 1977 event.

A. Identified in IE reports:

50-346/77-32

50-346/78-27, paragraph 2

50-346/78-30, paragraph 2 - unresolved item

50-346/78-12 and unresolved item (346/78-14)

2. Natural Circulation Test Results

A. Identified in IE reports:

50-346/78-30, paragraph 5

3. Core Lift Issue

A. Identified in IE report:

50-346/78-30, paragraph 6

4. Possible Operation at Power on Auxiliary Feedwater System

A. Identified in IE report:

50-346/78-30, paragraph 13

Commitments and response to commitments are addressed in the above references.

*J. S. Creswell*  
J. S. Creswell  
Reactor Inspector

cc: G. Fiorelli

POOR ORIGINAL