

SITE PROBLEM REPORT

BABCOCK & WILCOX

CUSTOMER Duke Power Co.	ORIGINATOR D. Culberson	DATE 6/7/78	DOC. ID. 13	CONT. NO. 620-0003	SPR NO. 679	REV. NO. 00
VENDOR Bailey	P.A. NO. NA		PART NO./TASK NO. 21	GROUP NO. 041	SEQ. NO. 004	
TITLE (MAX 30 CHARACTERS) ICS Module Failure - Rx Trip			PROBLEM CONTACT			

DESCRIPTION OF PROBLEM:

4/3/77 - Unit starting up following OTSG tube leak repairs.

1925 - High pressure Rx trip due to bad summer module in ICS (FDW Vlv. on "B" loop).

2030 - Re-commenced startup following module repair.

2158 - Generator on-line.

4/5/77 - 1110 - Unit at 100%.

(Information taken from R.Q. Log at Oconee I)

PROBLEM IDENTIFICATION

STATUS-ACTION TO DATE, INCLUDING PERSONS CONTACTED:

See above.

FURTHER ACTION RECOMMENDED BY SITE PERSONNEL:

None. Information only.

RESOLUTION:

CAPACITY

RESOLUTION

PREPARED BY <i>David A. Culberson</i>	DATE 6/12/78	APPROVED BY	DATE
REVIEWED BY	DATE		

COST CATEGORY <input type="checkbox"/> NORM    OTHER <input type="checkbox"/>	FIELD CHANGE REQ <input type="checkbox"/> YES    NO <input checked="" type="checkbox"/>	F.C.A. NO. 04- NA	SIGNIF. DEFICIENCY <input type="checkbox"/> YES    NO <input checked="" type="checkbox"/>
--	--	----------------------	--

SITE COMPLETION REPORT:

INFORMATION ONLY

COMPLETION

DEVIATIONS: <input type="checkbox"/> NONE	SPR REV NO. <input type="checkbox"/>
DATE COMPLETED: 4/3/77	
COMPLETED BY	DATE
8002100044 P	
SHEET	OF