



POOR ORIGINAL

Metropolitan Edison Company  
Post Office Box 480  
Middletown, Pennsylvania 17057  
717 941 4011

Writer's Direct Dial Number

February 19, 1980  
TLL 072

Office of Inspection and Enforcement  
Attn: Boyce H. Grier, Director  
Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pa. 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit II (TMI-2)  
Operating License No. DPR-73  
Docket No. 50-320  
Reportable Occurrence No. 80-06/LP

This telegram is to confirm the telecon between Mr. G. A. Kunder, Unit II Supervisor Technical Specification Compliance, and Mr. Rich Conti, Region I NRC at 1530 hours on February 19, 1980.

A situation considered reportable under Technical Specification 6.9.1.3.5 was entered on 1700 February 15, 1980. The Unit II Boric Acid Mix Tank (BAMT) was found to contain less than the required borated water per the new Recovery Technical Specification 3.1.1.1.3 Figure 3.1. This occurred due to the change in the requirements for minimum BAMT inventory over what previously was required by the previous TMI II Technical Specifications.

Further details and corrective action will be discussed in the following report.

Sincerely,

G. A. Kunder  
Supervisor Tech Spec Compliance

GAK:hah

cc: J. T. Collins

MOON  
5/10