



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

TIC
70-1201

80 05120263
C

MAR 21 1980

In Reply Refer To
RII:GPC
70-1201/80-5

Babcock and Wilcox Company
ATTN: Mr. W. F. Heer, Manager
Virginia Operations Nuclear Materials
and Manufacturing Division
Commercial Nuclear Fuel Plant (CNFP)
P. O. Box 800
Lynchburg, VA 24505

Gentlemen:

This refers to the inspection conducted by G. P. Coryell of this office on March 4-7, 1980 of activities authorized by NRC License No. SNM-1168 for the Commercial Nuclear Fuel facility, and to the discussion of our findings held with W. F. Heer at the conclusion of the inspection.


Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,


W. B. Kenna, Chief
Safeguards Branch

Enclosure:
Inspection Report No. 70-1201/80-5