

# LICENSEE EVENT REPORT

8005120367

CONTROL BLOCK: \_\_\_\_\_ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	E	M	Y	P	1	2	0	0	-	0	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4						5
LICENSEE CODE							LICENSE NUMBER													LICENSE TYPE JO					CAT 56									

CON'T

0	1	L	6	0	5	0	0	0	3	0	9	7	0	4	0	8	8	0	8	0	5	0	6	8	0	9
REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During routine surveillance testing of pump P-25A, auxiliary feedwater pump, a small

0 3 | quantity of oil was observed being discharged from the pump thrust bearing. Pump was

0 4 | manually shutdown after a seven minute run. The other auxiliary feedwater pump was

0 5 | verified to be operable. The event represents a reduction in degree of redundancy

0 6 | and since the other auxiliary feedwater pump remained operable, there was no effect

0 7 | on public health or safety.

0 8 | \_\_\_\_\_ 80

0	9	C	H	11	X	12	Z	13	P	U	M	P	X	X	14	B	15	Z	16
SYSTEM CODE			CAUSE CODE			CAUSE SUBCODE			COMPONENT CODE					COMP SUBCODE		VALVE SUBCODE			

  

17		8	0			0	1	0	/	0	3	L		0
LER NO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.				

  

Z	X	Z	Z		0	0	0	0	N	N	A	L	0	7	5
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS			ATTACHMENT SUBMITTED		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the event could not be determined, and the event could not be

1 1 | duplicated. Appropriate personnel have been instructed to be alert for a

1 2 | repetition of this type of event.

1 3 | \_\_\_\_\_

1 4 | \_\_\_\_\_ 80

E	28	0	9	7	29	NA	30	B	31	Routine Surveillance Testing	32
FACILITY STATUS		% POWER		OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		

Z	33	Z	34	NA	35	NA	36
ACTIVITY CONTENT		AMOUNT OF ACTIVITY			LOCATION OF RELEASE		

0	0	0	37	Z	38	NA	39
PERSONNEL EXPOSURES		DESCRIPTION					

0	0	0	40	NA	41
PERSONNEL INJURIES		DESCRIPTION			

Z	42	NA	43
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION	

M	44	NA	45
PUBLICITY ISSUED		DESCRIPTION	

NAME OF PREPARER James E. Brinkler

PHONE 207-882-6321

NRC USE ONLY