



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

FEB 17 1980

Docket No. 99900361/79-02

G. Dijkers and Company N.V.
Attn: Mr. C. S. Craig
Chief Executive
Industriestraat 15, P. O. Box 12
7550 AA Hengelo, Province of Overijssel
The Netherlands


Gentlemen:

Thank you for your letter of January 13, 1980, in response to our letter dated December 10, 1979. As a result of our review, we find that additional information is needed on the following items in the Notice of Deviation:

- C. This finding was written relative to procurement requirements for Conarc 49 electrodes, Charge No. 62373, which were noted during the inspection as having been used for repair welding of a bonnet, Charge No. 22.35.8 S/N 1. We trust that this information is sufficient for you now to provide the requested corrective action measures and steps to prevent recurrence.
- D. Please describe the method used to document re-instruction of QA Engineers in order to provide an auditable record of corrective action.
- E. Please describe the specific actions that have been taken or are planned to be taken, to assure that QC Inspectors are conversant with the responsibilities assigned to them by the manufacturing process control system contained in the QA Manual.

Please provide this additional information within twenty (20) days in order that we may complete our review in a timely manner.

Sincerely,


Uldis Potapovs, Chief
Vendor Inspection Branch

8005210400