

APPENDIX A

NOTICE OF VIOLATION

Pacific Gas and Electric Company
Docket No. 50-133

Based on the results of an NRC inspection conducted on March 24-28, 1980, it appears that certain of your activities were not conducted in full compliance with NRC regulations. Items A and B are Infractions, item C is a Deficiency.

- A. 10 CFR 20.203(c)(1), "Caution signs, labels, signals and controls", requires that each high radiation area be conspicuously posted with a sign or signs bearing the radiation caution symbol and the words: "Caution - High Radiation Area".

Contrary to this requirement, on March 26, 1980 the High Level Radioactive Waste Storage Vault was not conspicuously posted with a sign or signs bearing the words: "Caution - High Radiation Area". This matter was corrected at the time of the inspection.

- B. 10 CFR 20.203(c)(2)(iii), "Caution signs, labels, signals, and controls", requires that, in the absence of certain control devices, each entrance or access point to a high radiation area shall be maintained locked except during periods when access to the area is required with positive control over each individual entry.

1. Contrary to this requirement, on March 26, 1980 the south entrance door to Resin Regeneration Room was unlocked and positive control over each individual entry had not been established. The general area dose rate inside the room was measured to be 150 mRem/hr.

2. Contrary to this requirement, on March 26, 1980 a permanently installed ladder provided access to a high radiation area near Waste Receiver Tank No. 2. The measured dose rate near this tank was 800 mRem/hr.

These matters were corrected at the time of the inspection.

- C. 10 CFR 20.203(f)(1) and (2), "Caution signs, labels, signals and controls", requires that each container of licensed material shall bear a label showing the radiation caution symbol, the words, "Caution - Radioactive Material", and identification of the radioactive contents.

Contrary to this requirement, on March 26, 1980, two 4' x 4' x 8' wood boxes located in the restricted area north of the refueling building contained an estimated 2 millicuries each of licensed materials and did not bear a label.

This matter was corrected at the time of the inspection.

8005220335
Q