

Enclosure 1

Arkansas Power and Light Company
Arkansas Nuclear One, Units Nos. 1 and 2
Docket Nos. 50-313 and 50-368

NOTICE OF DEVIATION

Based on the results of an NRC inspection conducted during the period of February 22 through March 21, 1980, it appears that one of your activities was not conducted in accordance with your commitments to the Commission as indicated below:

Item 4 of IE Bulletin 79-21 required the licensee to "Review and revise, as necessary, emergency procedures to include specific information obtained from the review and evaluation of Items 1, 2 and 3 to ensure that the operators are instructed on the potential for and magnitude of erroneous level signals. All tables, curves, or correction factors that would be applied to post-accident monitors should be readily available to the operator. If revisions to procedures are required, provide a completion date for the revisions and completion date for operator training on the revisions."

The licensee's response to this Bulletin, dated September 24, 1979, included the following commitments with respect to Item 4:

"Response ANO-1

"Correction factors as appropriate from Tables 1-ANO-1 and 2-ANO-1 will be made readily available to the operators for post accident monitoring. Instruction will be provided as to its use. This will be completed by November 15, 1979.

"Response ANO-2

"Correction factors as appropriate from Tables 1-ANO-2 and 2-ANO-2 will be made readily available to the operators for post accident monitoring. Instruction will be provided as to its use. This will be completed by November 15, 1979."

Contrary to the above, the correction factors had not been made available to the operators of either Unit as of March 20, 1980.

This is a deviation. (313/80-05-01; 368/80-05-01)

8005270 340