NSTC



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I 631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

May 6, 1980

Docket Nos. 70-398 50-184

> U. S. Department of Commerce National Bureau of Standards ATTN: Dr. R. P. Bartlett Director, Administrative and Information Services Washington, D. C. 20234

Gentlemen:

Enclosed is IE Information Notice No. 80-19, "NIOSH Recall of Recirculating-Mode (Closed-Circuit) Self-Contained Breathing Apparatus (Rebreather)," which addresses the NIOSH "stop-sales-and-recall" order to the manufacturers of the BioPak 60P rebreather respirator. Should you have any questions related to the enclosed authorization or guidance, please contact this office.

Sincerely,

21/20 Bovce H. Grier

Director

Enclosures:

1. IE Information Notice No. 80-19

2. List of Recently Issued IE Information Notices

CONTACT: P. Knapp (215-337-5291)

## ENCLOSURE 1

SSINS: 6870 Accession No.: 8002280674

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

upe.

IE Information No. 80-19 Date: May 6, 1980 Page 1 of 1

NIOSH RECALL OF RECIRCULATING-MODE (CLOSED CIRCUIT) SELF-CONTAINED BREATHING APPARATUS (REBREATHER)

The NRC has been informed by the National Institute for Occupational Safety and Health (NIOSH), the agency that tests and certifies respirators, that some of the NIOSH-certified respiratory protective equipment that NRC licensees use might have been modified by the manufacturer without approval by NIOSH. NIOSH considers such modified equipment not to be certified, even though it might bear their test and certification label.

The equipment in question is the BioPak 30P and 60P, NIOSH test-and-certification numbers TC-13F-84 and TC-13F-85, respectively. The BioPak 30P and 60P are respectively 30-minute and 60-minute, closed-circuit, recirculating-mode, self-contained breathing apparatuses (rebreathers), manufactured by BioMarine Industries, Inc. Our information leads us to believe that NRC licensees have purchased only the 60P equipment.

NIOSH has issued a "stop-sales-and-recall" order to the manufacturer for this equipment. Licensees who have such equipment should check with the manufacturer to determine what action to take to assure that their equipment is in certified status.

The manufacturer's address and telephone number are:

BioMarine Industries Inc. 45 Great Valley Corporate Center Malvern, PA 19355

Tel: (215) 647-7200

## ENCLOSURE 2

IE Information Notice No. 80-19 Date: May 6, 1980 Page 1 of 1

## RECENTLY ISSUED IE INFORMATION NOTICES

| formation  | Subject  |              | Date   | Issued to  |
|------------|--|--------------|--|--|
| Notice No. |  |              | Issued   |  |
| 80-10      | Partial Loss of Non-Nuclear<br>Instrument System Power Sup-<br>ply During Operation                      |              | 3/7/80   | All Power Reactor Facil-<br>ities with an Operating<br>License (OL) or Construction<br>Permit (CP)                                   |
| 86-11      | Generic Problems With ASCO<br>Valves in Nuclear Applica-<br>tions including Fire Pro-<br>tection Systems |              | 3/14/80  | All Power Reactor Facil-<br>ities with an OL or CP,<br>Fuel Fabrication and<br>Processing Facilities                                 |
| 80-12      | Instrument Failure Causes 3/31/8<br>Opening of PORV and Block<br>Valve                                   |              | 3/31/80  | All Power Reactor Facil-<br>ities with an OL or CP   |
| 80-13      | General Electric Type SBM 4/2/80<br>Control Switches - Defective<br>CAM Followers                        |              | 4/2/80   | All Power Reactor Facil-<br>ities with an OL or CP   |
| 80-14      | Safety Suggestions from 4/2/80<br>Employees  |              | All Power Reactor Facil-<br>ities with an OL or CP,<br>Fuel Fabrication and<br>Processing Facilities and<br>Materials Pricrity 1 Licensees |  |
| 80-15      | Axial (Longitudinal)<br>Oriented Cracking in<br>Piping   | 4/21/80      |  | All Power Reactor Facil-<br>ities with an OL or CP   |
| 80-16      | Shaft Seal Packing<br>Causes Binding in Main<br>Steam Swing Check and<br>Isolation Valves                | 5/5/80       |  | All Power Reactor Facil-<br>ities with an OL or CP   |
| 80-17      | Potential Hazards<br>Associated With<br>Interchangeable Parts<br>On Radiographic Equipmen                | 5/5/80<br>nt |  | All Radiographic Licensees   |
| 80-18      | Possible Weapons<br>Smuggling Pouch  | 5/5/80       |  | All Power Reactor Faci-<br>lities with an OL, Fuel<br>Fabrication and Processing<br>Facilities and Materials<br>Priority I Licensees |