

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	J	A	F	I	2	0	0	-	0	0	0	0	-	0	0	0	3	4							4			5
7	8	14						15	25										26	30					57	CAT	58				
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE											

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 0 4 2 9 8 0 8 0 5 2 7 8 0 9

7 8 60 61 68 69 74 75 80

POCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, Rod Block Monitor A became inoperable when control rod
0 3 | 26-19 was selected due to an inadequate number of LPRM inputs. As required by
0 4 | TS Table 3.2-3, Note 1, Rod Block Monitor B was functionally tested immediately
0 5 | and daily thereafter until plant shutdown and a refueling outage started on
0 6 | 6 May 1980. The event did not represent a significant hazard to the public
0 7 | health and safety.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Rod block monitor A was made inoperable as a result of LPRM failures due to age. All

1 1 LPRM strings will be replaced during the current refuel and maintenance outage. No

1 2 additional action will be required.

1 3

1 4

7 2 9

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	3	1	29	A	31
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	NA	NA	36
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40		41	NA	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42		43	NA			
PUBLICITY		ISSUED		DESCRIPTION					
2	0	N	44		45	NA			
								NRC USE ONLY	

NRC USE ONLY

NAME OF PREPARER

W. Verne Childs 8006020396

PHONE

315-342-3840