LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58 5
CON'T 0 1 SOURCE L 6 0 5 0 - 0 3 2 4 7 0 5 0 7 8 0 8 0 6 0 3 8 0 9 7 8 SOURCE 50 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9
During the current refueling outage, PT 15.6, Standby Gas Treatment Operability
Test, was not performed by the required date of April 25, 1980. This event did
not affect the health or safety of the public.
, 12
0 7
Technical Specification 6.9.1.9c 7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
SYSTEM CODE CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE
17 REPORT NUMBER 21 22 23 PREPORT NO. 10 3 L - 0 0 0 0 0 0 0 0 0
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER H 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
The PT was not performed due to an administrative oversight. It was satisfactorily
performed on May 7, 1980. The administrative system for performing surveillance
tests was reviewed and is considered adequate. This event appears to be an isolated
event. All Operations personnel responsible for performing or reviewing Operations
surveillances were reminded to exercise care in a memo from the Manager - Operations.
FACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5
ACTIVITY CONTENT RELEASED OF RELEASE 1 6 Z 33 Z 34 N/A PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 N/A N/A 10 N/A 10 N/A 10 N/A
1 7 8 9 PERSONNEL INJURIES 13 80
NUMBER DESCRIPTION (41) NO 0 0 0 40 N/A 1 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A N/A N/A 80
PUBLICITY ISSUED DESCRIPTION 45 N/A 8006090355
7 8 9 10 68 69 80.5 NAME OF RESPARSE A. C. Tollison, Jr. 919-457-9521 2