## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:                 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 0 R T N P 1 2 0 0 0 - 0 0 0 0 0 4 1 1 1 1 1 1 0 5 57 CAT 58
CON'T    REPORT   L   6   0   5   0   -   0   3   4   4   7   0   5   1   6   8   0   8   0   5   3   0   8   0   9     SOURCE   SO   61   DOCKET NUMBER   68   69   EVENT DATE   74   75   REPORT DATE   80
[0] NO. 80-08: DURING REFUELING OPERATIONS IT WAS DISCOVERED THAT CONTAINMENT
[0] INTEGRITY WAS BREACHED. A PATHWAY EXISTED TO ATMOSPHERE VIA AN OPEN STEAM
GENERATOR SECONDARY MANWAY AND A DISASSEMBLED MAIN STEAM ISOLATION VALVE.
THERE WERE NO ADVERSE CONSEQUENCES BECAUSE THE CONTAINMENT IS MAINTAINED
O 6 AT A NEGATIVE PRESSURE.
07
7 8 9
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
17) LER/RO EVENT YEAR SEQUENTIAL REPORT NO. REPORT NO. PEPORT NO. POLICY NO. 121 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRO- PRIME COMP. COMPONENT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
H (8) Z (9) Z (20) Z (21) 10 0 0 0 1 2 2 2 2 2 36 2 2 36 2 2 36 2 2 2 36 2 2 2 36 2 2 2 36 2 2 2 36 2 2 2 36 2 2 2 36 2 2 2 36 2 2 2 36 2 2 2 36 2 2 2 2
THIS OCCURRENCE WAS CAUSED BY PERSONNEL ERROR. TWO SEPARATE MAINTENANCE
ACTIVITIES WERE BEING PERFORMED AND THERE WAS NO COORDINATION BETWEEN THEM
SCHEDULING PERSONNEL HAVE BEEN INSTRUCTED TO PREVENT THIS FROM RECURRING.
ŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢŢ
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32    1   5   H   28   O   O   O   29   NA   ACTIVITY CONTENT 12 13   45   46   WORKMAN OBSERVATION   90
RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
NUMBER TYPE DESCRIPTION (39)  1 7 8 9 PERSONNEL INJUSTES 13  80
1 8 O O O O O NA
LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION NA  NA
PUBLICITY ISSUED DESCRIPTION 45 NA NAC USE ONLY
NAME OF PREPARER John C. Perry PHONE: (503)556-3713, extension 228