1.18

June 6, 1980

Mr. James G. Keppler Regional Director Directorate of Regulatory Operations Region III U.S. Nuclear Regulatory Commission Glen Ellyn, Illinois 60137

Reference: Zion Generating Station Docket No. 50-295/DPR-39

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/80-23 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telegram/mailgram on 5/25/80.

This report is submitted to you in accordance with the requirements of the Technical Specification, Section 6.6.2.a.9 which says that performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report require a 14-day written report.

Very truly yours,

N. E. Wandke Superintendent Zion Station

JJM/kjk

Enclosure: Reportable Occurrence Report No. 50-295/80-23

A002 5 980 1/1