



MATERIAL TRANSMITTED HEREWITH  
CONTAINS SENSITIVE INFORMATION  
UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA ST., N.W., SUITE 3100  
ATLANTA, GEORGIA 30303

APR 21 1980

Report No. 70-1151/80-10

Docket No. 70-1151 License No. SNM-1107 Safeguards Group III

Licensee: Westinghouse Electric Corporation  
Nuclear Fuel Division  
Columbia, SC 29205

Facility: Westinghouse Electric Corporation

Inspection at: Columbia, SC

Inspection conducted: March 25-28, 1980

Date of Last Material Control and Accounting Inspection Visit: February 11-15, 1980

Type of Inspection: Unannounced Material Control & Accounting

Inspector: J. W. Bates  
J. W. Bates, Chemist

4/21/80  
Date

Approved by: F. P. Gillespie  
F. P. Gillespie, Chief, MC&A Section  
Safeguards Branch

4/21/80  
Date

Inspection Summary:

Areas Inspected: The Westinghouse Measurement Control Program.

The inspection involved 28 inspector-hours on site by one NRC inspector and was begun during the regular hours.

Results: The licensee was found to be in compliance with NRC requirements in the one area examined during the inspection except for the following two items:

1. Failure to initially calibrate the emission spectrometer with standards traceable to a national system of standards (80-10-01) (deficiency).
2. Failure to record actions taken when control data exceeded the .05 control limit (80-10-02) (deficiency).

S-F2 80 - 50P  
Copy \_\_\_\_\_ of \_\_\_\_\_ Copies  
17 Pages  
This Document is not to be  
reproduced without specific  
approval of IE:II

8006200015