

NOTICE OF VIOLATION

Young Wireline Service, Inc.
Charleston, West Virginia

Docket No. 030-20532
License No. 47-21351-01

As a result of the inspection conducted on June 12, 1989, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1989), the following violations were identified:

- A. 10 CFR 39.35(c) requires that sealed sources be tested for leakage at intervals not to exceed six (6) months.

Contrary to the above, between July 1988 and June 12, 1989, an interval greater than six months, three sealed sources (two Americium-241 and one Cesium-137) were not tested for leakage.

This is a Severity Level IV violation (Supplement IV).

- B. 10 CFR 39.37 requires that a semiannual physical inventory be conducted to account for all licensed material received and possessed.

Contrary to the above, between July 26, 1988, and June 12, 1989, the required semiannual inventory was not conducted.

This is a Severity Level IV violation (Supplement IV).

- C. 10 CFR 39.65(a) requires that film badges be processed promptly after replacement.

Contrary to the above, a film badge assigned to a logging supervisor was not processed promptly after replacement in April 1989, and consequently became lost and never evaluated.

This is a Severity Level IV violation (Supplement IV).

- D. 10 CFR 39.73 requires that the licensee maintain the following documents and records at the field station:

- a. A copy of Parts 19, 20, and 39 of NRC regulations.
- b. Operating and emergency procedures required by 10 CFR 39.63.
- c. The records of radiation survey instrument calibrations required by 10 CFR 39.33.
- d. The record of leak test results required by 10 CFR 39.35.
- e. Physical inventory records required by 10 CFR 39.37.
- f. Records of inspection and maintenance required by 10 CFR 39.43.
- g. Training records required by 10 CFR 39.61(d).


8911130222 891103
REGD LIC30 PNU
47-21351-01

Contrary to the above, as of June 12, 1989, the above-referenced documents and records have not been maintained at the Bradford, Pennsylvania, Field Station.

This is a Severity Level V violation: (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, Young Wireline Service, Inc., is hereby required to submit a written statement or explanation to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, within 30 days of the date of the letter transmitting this Notice. This reply should be clearly marked as a "Reply to a Notice of Violation" and should include [for each violation]: (1) admission or denial of the violation, (2) the reason for the violation if admitted, (3) the corrective steps which have been taken and the results achieved, (4) the corrective steps which will be taken to avoid further violations, and (5) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked or why such other action as may be proper should not be taken.

FOR THE NUCLEAR REGULATORY COMMISSION



For
William E. Cline, Chief
Nuclear Materials Safety and
Safeguards Branch
Division of Radiation Safety
and Safeguards

Dated at Atlanta, Georgia
this 3rd day of November 1989