



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

December 17, 1971

J. B. Henderson, Chief, Reactor Construction Branch
Division of Compliance, Headquarters

TOLEDO EDISON COMPANY (DAVIS-BESSE)
DOCKET NO. 50-346
STRUTHERS NUCLEAR AND PROCESSING COMPANY

The attached report of a licensee-vendor audit, surveillance inspection at the subject vendor's plant on December 6 and 7, 1971, is transmitted for information. No items of noncompliance, nonconformance, or significant problems were encountered.

In the opinion of our inspector, the licensee representatives were well prepared and fully qualified to perform the audit. The inspector also concludes that the audit was performed in a thorough and effective manner.

A handwritten signature in cursive script, reading "W. E. Vetter", is written above the typed name.

W. E. Vetter
Senior Reactor Inspector

Attachment:
CO Rpt No. 050-346/71-04 by
T. E. Vandel (2 cys)

cc: E. G. Case, DRS (3)
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRL (2)
✓ A. Giambusso, CO
✓ L. Kornblith, CO
✓ R. H. Engelken, CO
Regional Directors, CO
DR Central Files

8001310 622

1 5361