



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137
August 31, 1971

TELEPHONE
(312) 858-2660

J. B. Henderson, Chief, Reactor Construction Branch
Division of Compliance, Headquarters

TOLEDO EDISON COMPANY (DAVIS-BESSE)
DOCKET NO. 050-346

The attached report of an announced inspection at the subject facility construction site on June 8-10, 1971, is transmitted for information. No significant safety problems were encountered but two apparent items of nonconformance were discussed with the applicant at the conclusion of the inspection.

Although a conclusive evaluation could not be made at the time of the inspection, it appears that the shield building wall may be slightly more out of plumb than permitted by the specifications. We intend to review additional data to be made available during our next routine inspection which should lead to resolution of this matter.

A handwritten signature in cursive script that reads "W. E. Vetter".

W. E. Vetter
Senior Reactor Inspector

Attachment:
CO Rpt No. 050-346/71-02 by Jones
and Hayes (2 cys)

cc: E. G. Case, DRS (3)
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRL (2)
A. Giambusso, CO
L. Kornblith, CO
R. H. Engelken, CO
Regional Directors, CO
DR Central Files

8002030190

1 4399

gd