

UNITED STATES ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE

REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE: 526-4537

FEB 1 3 1969

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch Division of Compliance, Headquarters

FLORIDA POWER CORPORATION (CRYSTAL RIVER NO. 3), LICENSE NO. CPPR-51, DOCKET NO. 50-302

Transmitted herewith for information is Compliance Report No. 302/69-1 covering a routine inspection on January 23-24, 1969. There was one item of nonconformance observed relating to a change in the foundation design. This was a substitution of 1500 psi concrete for crushed lime rock. The licensee stated this would be justified in the FSAR. We believe concrete is more desirable for this application.

We anticipate some problems in the area of site quality control due to inexperience of existing personnel in nuclear-type work. We will continue to follow this matter.

CO:II:FJL

Enclosure: CO Report No. 302/69-1 (Bryant)

cc: E. G. Case, DRS

R. S. Boyd, DRL (2)

S. Levine, DRL (6)

D. J. Skovholt, DRL (3)

L. Kornblith, Jr., CO

R. W. Kirkman, CO:I

B. H. Grier, CO:III

D. I. Walker, CO:IV

R. W. Smith, CO:V

REG Files

9 0524

Senior Reactor Inspector

9