

## OMIC ENERGY COMMISSION WASHINGTON, D.C. 20545

RO f:60

JUN 19 1974

E. J. Brunner, RO:I

W. C. Seidle, RO:II

C. E. Murphy, RO:II

G. S. Spencer, RO: V

## FLOW ORIFICE DESIGN DEFICIENCY

Enclosed for your information and possible action are copies of CDR#247 and an evaluation memorandum prepared by TAB concerning the subject deficiency.

We concur in TAB's recommendation that RO inspection attention be provided to assure orifice replacement at the affected facilities.

Harold D. Thornburg, Chief

Field Support & Enforcement Branch Directorate of Regulatory Operations

NT4.6 150-313