



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION II - SUITE 916
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30302

TELEPHONE 404 526-4000

January 15, 1973

J. B. Henderson, Chief, Reactor Construction Branch (2)
Directorate of Regulatory Operations, Headquarters

RO INQUIRY REPORT NO. 50-313/73-1Q/CDR
ARKANSAS POWER AND LIGHT COMPANY (ARKANSAS NUCLEAR ONE, UNIT 1),
LICENSE NO. CPPR-57, DOCKET NO. 50-313, LACK OF MATERIAL CONTROL -
WELD FILLER MATERIAL

Attached Inquiry Report No. 50-313/73-1Q/CDR is for information. The problem appears to be generic, and as reported to Region II, B&W is treating it as such and notifying other affected licensees.

The corrective action indicated appears to be clear; however, we will examine any corrective measures implemented to resolve the immediate problem and eliminate recurrence during a subsequent inspection. You may also include the item in your next routine vendor inspection at Barberton.

F. J. Long, Chief
Facilities Construction Branch

8004150 835