



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE 404 528 4503

APR 25 1973

→ J. B. Henderson, Chief, Construction Branch (2)
Directorate of Regulatory Operations, Headquarters

RO INQUIRY REPORT NO. 50-313/73-2Q
ARKANSAS POWER AND LIGHT COMPANY (ARKANSAS NUCLEAR ONE, UNIT 1),
LICENSE NO. CPPR-57, DOCKET NO. 50-313, MOTOR CONTROL CENTER -
REVERSING STARTER

Attached Inquiry Report No. 50-313/73-2Q is for information. The problem is generic to Allis-Chalmers (A-C) Size 1 reversing starters. A-C is changing out parts with excessive tolerance.

The corrective action indicated should resolve the problem pending replacement of suitable parts. We will examine the corrective measures implemented and measures enacted to prevent recurrence of the problem during a subsequent construction inspection.

You may wish to include the item in your next routine vendor inspection of A-C.

F. J. Long, Chief
Facilities Construction Branch

late.

~~8004170625~~

8004170625