A Branch of The East Hartford Pladiology Group, P. C. 300 HEBRON AVENUE / GLASTONBURY, CT 06033 / 659-0555

August 2, 1989

Docket No. 030-30365 re: your letter of July 5, 1989 License No. 06-28141-01

Mohamed M. Shanbaky, Chief Nuclear Materials Safety Section A Division of Radiation Safety and Safeguards USNRC Region 1 475 Allendale Road King of Prussia, PA 19406

Dear Dr. Shanbaky:

Accuracy and linearity checks of our dose calibrator were not performed prior to February 9, 1989. We recognize that it was wrong to measure patient doses before this was done. In April we hired a new radiation safety consultant who recognized this deficiency and sought to correct it by performing the appropriate checks, albeit late. The accuracy and linearity checks proved acceptable, so we are reasonably certain that no misadministrations took place. We believe we were in full compliance at the time of Mr. Kirkwood's inspection on May 5.

Although we cannot rewrite history, we ask that you consider the corrective action taken prior to the inspection, and reverse the finding of a lack of full compliance. Since we have contracted for monthly physics consulting services, we do not expect any future deviations from NRC requirements.

Thank you for your consideration.

Sincerely,

James A. Danigelis, M.D.
Radiation Safety Officer

3910310056 891017 REG1 LIC30 06-28141-01 PNU

COLBY S. STEARNS, M.D.
LYMAN B. FOGG, M.D.
JONATHAN BERGER, M.D.
JAMES A. DANIGELIS, M.D.
HELENA CIHAK, M.D.
DEEPAK BRAMHAVAR, M.D.
VIJAY SANKHLA, M.D.