SEP 3 1974 50

H. D. Thornburg, Chief, Field Support and Enforcement Branch, RO

PROPOSED RO BULLETIN - MISAPPLICATION OF CRANE COMPANY 10 INCH 300 POUND CAST ALLOY STEEL VALVE, CATALOG NO. 151 1/2 LU IN PWR PLANTS SUPPLIED BY BEW

Review of UE-270/74-3 submitted by the licensee and RO Inquiry Report 50-269/72-5 indicates three valve internal failures in a two year period. Failure was not due to design deficiencies, but due to its being used as a throttle valve when its intended use, as stated by the manufacturer, is as a stop valve.

The valves that failed were installed in the low pressure injection system and were being used to throttle flow during decay heat removal. In normal operation, the valve is in the full open position.

It is our recommendation that the attached bulletin be sent to all PWR plants, supplied by B&W, for action.

If you require further information on this subject, please contact J. A. Dyer on Extension 7421.

eg/ Seyfit

Technical Assistance Branch

Directorate of Regulatory Operations

Attachment: As Stated

cc: J. G. Davis

B. H. Grier

10 A 80	ROSTIA	
JADyer:b	1000	
JADyer:b	s KVSeyfrit	
9/3/74	9/3/74	