

APPENDIX A

NOTICE OF VIOLATION

Duke Power Company

License Nos. DPR-38
DPR-47
DPR-55

Based on the results of the NRC inspection on October 11-19, 1977, it appears that certain of your activities were not conducted in full compliance with NRC facility license Nos. DPR-38, DPR-47 and DPR-55 as indicated below.

- A. Technical Specification 6.41 states that the station shall be operated and maintained in accordance with approved procedures and that written procedures with appropriate check-off lists and instructions shall be provided, in part, for Emergency Procedures involving potential or actual release of radioactivity, and Radiation Control procedures. Health Physics procedure, HP/O/B/1009/04, "Scott Air Paks II and III, Self Contained Breathing Apparatus," requires that all Scott Air Paks be thoroughly inspected once per month and the inspection information be placed on a tag on the case.

Contrary to the above, on October 12, 1977, an inspector observed the inspection tags on two Scott Air Paks in Unit 1 and 2 control room which indicated they had not been inspected during June, August, September and December of 1976 and February, March and August of 1977. Two Scott Air Paks in Unit 3 control room and one Scott Air Pak in the administrative building first aid room had inspection tags which indicated similar missing inspection dates. This is an infraction.

- B. Technical Specification Table 4.1-1 requires a monthly battery check and annual calibration of emergency survey instruments.

Contrary to the above on October 12, 1977, an inspector observed that the emergency survey instruments HP 69-2 in Unit 3 control room and HP 69-1 in Units 1 and 2 control room had apparently last received a monthly battery check on March 24, 1977 and May 4, 1977, respectively. This is a deficiency.

8001031049