

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

IE FILE COPY

NOV 11 1976

The Tolado Edison Company
ATTN: Mr. Lowell E. Roe
Vice President
Facilities Development
Edison Plaza
300 Madison Avenue
Toledo, Ohio 43652

Docket No. 50-346

Gentlemen:

Thank you for your final reports pursuant to 10 CFR Part 50.55(a):
(1) Report dated October 19, 1976, relative to General Electric Company
type AK 480volt AC circuit breakers; (2) report dated October 26, 1976,
relative to the emergency diesel generator jacket cooling water heat
exchangers; and (3) report dated October 27, 1976, relative to Westing-
house type DHP 4.16 KV switchgear. We will review these matters during
a future inspection.

Your report dated October 27, 1976, and the referenced interim report
dated October 25, 1976, concerning reactor coolant pump seal injection
isolation valve (MHHV66B) have been received and reviewed. Further
information, as required by 10 CFR Part 50.55(a)(3) relative to the
cause of the failure and the safety implications, is necessary.

We understand, based on discussions by our inspectors with site per-
sonnel, that the yoke for valve MHHV66B has failed twice, and this
information should be included in your report as part of the evaluation.

Your cooperation with us is appreciated.

Sincerely yours,

R. F. Heishman, Chief
Reactor Construction and
Engineering Support Branch

cc: Dr. Ernst Volgenau
Director of Inspection
and Enforcement

bcc w/ltrs dtd 10/19, 25, 26,
and 27/76:
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC 8001300672
U. Young Park, Power
Siting Commission

