

UNITED STATES ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

TELEPHONE (312) 858-2660

March 10, 1972

J. B: Henderson, Chief, Reactor Construction Branch Division of Compliance, Headquarters

VENDOR INSPECTION REPORT
DRESSER INDUSTRIES, ALEXANDRIA, LOUISIANA

MAIN STEAM SAFETY VALVES TOLEDO EDISON COMPANY (DAVIS-BESSE) DOCKET NO. 50-346

The attached report of a vendor inspection at the subject manufacturing plant on February 23 - 24, 1972, is transmitted for information. No items of noncompliance, nonconformance, or safety problems were identified during the inspection.

You will note that Section 9 of the report contains information which may be considered by the manufacturer to be company private or proprietary.

W. E. Vetter

Senior Reactor Inspector

Attachment:

CO Rpt No. 999-54/72-01 by

R. E. Oller

cc: E. G. Case, DRS (3)

R. S. Boyd, DRL (2)

R. C. DeYoung, DRL (2)

D. J. Skovholt, DRL (3)

H. R. Denton, DRL (2)

L. Kornblith, CO

R. H. Engelken, CO

CO Files

DR Central Files