UNITED STATES

## LEAR REGULATORY COMMISSION

RECION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

November 5, 1975

The III Files AF

Region III Files

THRU: D. W. Hayes, Senior Reactor Inspector, Projects Section

DAVIS-BESSE UNIT 1 SITE INSPECTION OCTOBER 29 AND 30, 1975

J. W. Sutton and I. T. Yin conducted a scheduled, announced inspection of construction activities on October 29 and 30, 1975.

Mr. W. J. Dircks, Assistant Executive Director for Operations, Headquarters, accompanied the inspectors.

A summary of Mr. Dircks' activities and expressed interests during the inspection are identified below:

- 1. Mr. Dircks was given the following documents for his personal use:
  - a. Current inspection plan, dated October 22, 1975.
  - b. Report of the last Davis-Besse inspection (Report No. 050-346/75-18).
  - c. Summary of Licensing's October 15 and 16, 1975, site electrical technical review findings.
  - d. Brief description of the plant, license status, and major issues.
- Mr. Dircks also reviewed IE Inspection Reports No. 050-346/75-09, No. 050-346/75-10, No. 050-346/75-13, No. 050-346/75-15, and No. 050-346/75-16.
- 3. Areas of interest, as expressed by Mr. Dircks during the inspection, were as follows:
  - personnel present, and freedom to talk with employees.
  - b. Procedures and methods used by the inspectors in obtaining information from the licensee, and time and problems involved in obtaining this information.

- c. Significant problem areas at the site (electrical, primary coolant pumps, and containment paint).
- d. Inspector's relationship with the licensee relative to communication channels, responsiveness, etc.
- e. Criteria of conducting exit interviews.
- f. The idea of Licensing personnel being stationed in the regions.
- Licensing personnel. (I.e., the flow of information and mutual notification of problem areas, etc.)
- The inspectors also discussed their backgrounds and experiences, workloads, inspection module concepts, Yellow Book preparations, etc.

The inspectors informed Mr. Direks that this inspection was a typical inspection, using the techniques normally employed by IE:III personnel.

5. Mr. Direks accompanied Mr. Sutton during his field review of the licensee's corrective action on previously reported violations/infractions and the review and observation of the baseline in-service inspection of the pressurizer welds. He accompanied Mr. Yin during his review of the snubber/hanger installation program and examination of actual installations.

At the conclusion of the inspection, Mr. Direks indicated that he was satisfied with the conduct of the inspection and had seen and been informed in all areas of his interest.

. W. Sutton

Reactor Inspector, Projecta Section

D. M. Hunnicutt

