JAN 17 .8

Docket No. 50-329/77-12 Docket No. 50-330

Consumers Power Company
ATTN: Mr. Stephen H. Howell
Vice President
1945 West Parnall Road
Jackson, MI 49201

Centlemen:

Our letter dated January 10, 1978, transmitted an inspection report referring to the inspection conducted on Movember 29 - December 2, and December 5-8, 1977. The inspection number was in error. Please replace page 2 of the transmittal letter and page 1 of your copy of the report with the enclosed corrected pages.

We regret any inconvenience this may have caused.

Sincerely.

R. F. Heislman, Chief Reactor Construction and Engineering Support Branch

Enclosures: Corrected copies

cc w/encls:
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Ronald Callen, Michigan
Public Service Commission
Dr. Wayne E. North
Myron M. Cherry, Chicago

NEC FORM 318 (9-76) NECM 0240

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

	8006200688					
DFFICE	RIII	RIIL	RIII	RIII LTHAD	RIII //	This is
BURNAME	Cook/jb	Naidu	Hayes	Danielson	Heishmen	
DATE	1/16/78	,/	/	1/16/78		

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. F. Heishman, Chief Reactor Construction and Engineering Support Eranch

Enclosure: IE Inspection keports No. 50-329/77-12 and No. 50-330/77-15

cc w/encl:
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Ronald Callen, Michigan
Public Service Commission
Dr. Wayne E. North
Myron M. Cherry, Chicago

10

U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Report No. 50-329/77-12: 50-330/77-15

Docket No. 50-329, 50-330

License No. CPPR-81, CPPR-82

Licensee: Corsumers Power Company

1945 West Parnall Road Jackson, MI 49201

Facility name: Midland Nuclear Power Plant, Units 1 and 2

Inspection at: Midland Site, Midland, MI

Inspection conducted: November 29-December 2, and December 5-8, 1977

Inspectors: R. J. Cook

12211

JAK. R. Naidu

Approved by: D. W. Hayes, Chief

Projects Section

1/10/78

1/10/75

Inspection Summary

Inspection on November 29-December 2, and December 5-8, 1977 (Report No. 50-329/77-12; 50-330/77-15)

Areas Inspected: Work activities and quality records related to concrete placement Unit 1; procedures, quality records and work activities related to the installation of safety related components Units 1 and 2; procedures and quality records related to containment structural steel, safety related structural steel and welding activities Units 1 and 2. This inspection involved a total of 81 inspector-hours onsite by two NRC inspectors. Results: No items of noncompliance or deviations were identified.