

JUL 14 1976

D. M. Hannicutt, Chief, Reactor Construction and
Engineering Support Branch, IE:III

EVALUATION OF NONCONFORMING REINFORCING STEEL AT CONSUMERS POWER
COMPANY, MIDLAND, UNITS 1 AND 2, DOCKET NOS. 510-329/330 (AITS F30182H1)

Enclosed is the report of the inspection completed by R. Shewmaker of
my staff on June 24 and 25, 1976, when he accompanied I. Yin of your
staff to the Bechtel offices in Ann Arbor, Michigan. This assistance
on the above subject was provided in response to a request contained
in a letter directed to me by D. W. Hayes, dated May 4, 1976.

The enclosed report can either be used as is for a details section or
integrated into a larger report which your office might wish to prepare.

In summary, *it* has been concluded that the sixteen items listed in
the May 4, 1976 letter should be considered as resolved.

Karl V. Seyfrit, Chief
Reactor Technical Assistance Branch
Office of Inspection and Enforcement

Enclosure:

Details Section: Inspection at
Bechtel (Ann Arbor) on Midland, Units 1 and 2

cc w/enclosure:
R. Warnick, IE:HQ

RIP 681 F3 0182 H1

IE:RTB IE:RTB

RESheemaker KVSeyfrit

7/ /76 mak 7/ /76

8006250 416