

APPENDIX A

NOTICE OF VIOLATION

Boston Edison Company

Docket No. 50-293

Based on the results of an NRC inspection conducted on April 22-30, 1980, it appears that one of your activities was not conducted in full compliance with your NRC Facility License No. DPR-35, as indicated below. This item is categorized as a deficiency.

Technical Specification 6.8.A states that: "Written procedures...shall be established, implemented and maintained that meet or exceed the requirements and recommendations of Sections 5.1 and 5.3 of ANSI N18.7-1972..."

ANSI N18.7-1972, Section 5.3.5(1), states in part that: "...When entry is required into a closed system where the presence of foreign material is intolerable, control measures shall be established to prevent entry of extraneous material and to assure that foreign material is removed from these systems."

Station procedure TP 80-38, Feedwater Check Valve Overhaul, March 27, 1980, Section VI, Precaution B, states in part: "keep valve openings covered when work is not being performed inside the valve." Precaution J further states that "a tool control log shall be maintained for all tools and equipment entering and leaving the work area."

Contrary to the above, on April 24, 1980, the Feedwater Check Valves were opened for maintenance without covers over non-attended openings and with no tool control log in effect.

8007280 258