

NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

A R A N O		0 0 - 0 0 0 0 - 0 0		3 4 1 1 1 1		4 5	
LICENSEE CODE		LICENSE NUMBER		LICENSE TYPE		CAT 56	
CON'T							
REPORT SOURCE		DOCKET NUMBER		EVENT DATE		REPORT DATE	
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES							
Based on piping system as-built configuration review as required by I.E.							
Bulletin 79-14, the attached list of 17 hangers were declared inoperable.							
System redundancy was maintained in every case. A hanger design change							
was immediately prepared to upgrade the affected hanger to meet design							
requirements. LER's 50-313/79-010 and 80-010 were similar occurrences.							
Reportable per T.S. 6.12.3.2.b.							
SYSTEM CODE		CAUSE CODE		COMPONENT CODE		VALVE SUBCODE	
X X		B		S U P P O R T		Z	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		REVISION NO.	
8 0		-		0 1 1		4	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD	
F X		Z		Z		HOURS	
ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER	
Y		Y		A		B 1 3 0	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS							
The affected hangers were repaired or modified within the time frame							
allowed by Tech Spec. All design changes were governed by DCP 80-D-1007							
and its amendments. The affected systems were Service Water (WA), Main							
Steam (CC), Decay Heat (CF), Makeup (PC), and Emergency Feedwater (WB).							
Bulletin review continuing.							
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY	
E		1 1 0 0		NA		Notification from A/E	
ACTIVITY CONTENT		RELEASED OF PRESSURE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
G		Z		NA		NA	
PERSONNEL EXPOSURES		TYPE		DESCRIPTION			
0 0 0		Z		NA			
PERSONNEL INJURIES		NUMBER		DESCRIPTION			
0 0 0		NA					
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION			
Z		NA					
PUBICITY		ISSUE(1)		DESCRIPTION		NRC USE ONLY	
N		NA					
NAME OF PREPARER Lindsley S. Bramlett PHONE: 501/968-2519							

8008080270

HANGERS DECLARED INOPERABLE

<u>Hanger Number</u>	<u>System</u>
HBD-14-H35	Service Water
HBD-14-SW20	Service Water
MS-175	Main Steam
HBD-20-H15	Service Water
HBD-14-H2	Service Water
MS-156	Main Steam
GCB-1-41	Decay Heat
DH-100	Decay Heat
DH-95B	Decay Heat
DH-148	Decay Heat
DH-146	Decay Heat
DH-F-1	Decay Heat
DH-F-8	Decay Heat
MU-219	Makeup
HBD-2-H2	Service Water
HBD-4-H17	Emergency Feedwater
EFW-53	Emergency Feedwater