LICENSEE EVENT REPORT

**	CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [
0 1	T IN S N PI 2 0 0 - 10 0 0 0 - 10 0 25 26 LICENSE TYPE 30 57 CAT 56
CONT	SOURCE L 6 0 5 0 0 0 3 2 7 7 0 7 0 6 8 0 8 0 8 0 8 0 9 69 EVENT DATE 74 75 REPORT DATE 80
0 2	DURING NORMAL OPERATION, 1-LCV-3-148 FAILED IN THE OPEN POSITION. THIS RENDERED THE
0 3	AUXILIARY FEEDWATER 1B-B TRAIN MOTOR TO STEAM GENERATOR # 3 INOPERABLE. THIS RESULTED
0 4	IN ENTERING THE ACTION STATEMENT OF LCO 3.7.1.2.
0 5	
0 6	
0 7	
7 3	SYSTEM CAUSE CAUSE COMP. VALVE
0 9	CODE SUBCODE S
	1) REPORT VEAR S O 1 1 1 7 0 3 1 0 32 1 1 1 7 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	ACTION FUTURE COMPONENT SHUTDOWN HOURS 22 ATTACHMENT PORMSUB. SUPPLIER MANUFACTURER X 18 Z 19 Z 20 Z 21 10 10 10 10 10 10 10
[1]0]	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) INVESTIGATION REVEALED A BAD COIL ON THE CONTROL TIMER AND A GROUND WAS LOCATED IN
	11-PS-3-148. THE COIL WAS REPLACED, THE GROUND WAS CLEARED AND 1-PS-3-148 WAS RECALIBRATED
	AND THE SYSTEM WAS RETURNED TO SERVICE. THE GROUND ON 1-PS-3-148 WAS DETERMINED NOT TO
1 2	HAVE CAUSED THE VALVE TO FAIL OPEN. THE SYSTEM WAS INOPERABLE FROM 6:30am TO 4:00pm.
113	WHICH IS WITHIN THE ACTION STATEMENT OF 72 HOURS.
7 - 6	TATUS STATUS (30) METHOD OF DISCOVERY DESCRIPTION (12)
7 8	90 10 12 11 44 45 46
1 6	ELEASED OF RELEASE (36) Z (33) Z (34) NA SERSONNEL EXPOSURES NA LOCATION OF RELEASE (36) NA 45
17	NUMBER OF SCRIPTION (39) NA NA
ा ह	PERSONNEL INJURIES NUMBER DESCRIPTION (1) 10 10 10 1(40) I NA
, 3	LOSS OF OR DAMAGE TO FACILITY (43)
19	Z 42 OESCRIPTION NA
	PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA NA NA NA NA NA N
7 8	Name of Pranarar Dean Romine 8008110377Phone