LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CONTROL BLOCK - 0 0 0 0 0 0 - 0 0 1 CON'T 0 (8) 0 418 1001712 0 5 0 0 0 1 E' E'T DESCRIPTION AND PROBABLE CONSEQUENCES (10) At 0730 on 7/23/80, diesel generator (D.G.) 1C was declared inoperable | 0 2 when it failed to reach rated speed and voltage (13.5 seconds and 11.5 0 3 seconds respectively vs. 10+1 seconds required). Tech. Spec. 3.8.1.1, 0 4 in part, requires D.G. 1C to be operable. A similar occurrence was 0 5 The health and safety of the public reported in LER 80-043/03L-0. 0 6 were not affected. 0 7 0 8 CO...b SUBCODE SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE CODE SUBCODE CODE REVISION OCCURRENCE SEQUENTIAL REPORT CODE TYPE NO. REPORT NO. ER RO 0 0 3 TROSE 4 ..."8EA COMPONENT HOURS (22) SUPPLIER MANUFACTURER FORM SUB METHOD N 24 0 1 1 Y 23 01 10 13) X Z USE DESCRIPTION AND CORRECTIVE ACTIONS (27) IC failure to reach rated speed and voltage within the required The cause for D.G. time is under continued investigation. This is the fourth LER reported since March 31, 1980 on occurrences similar to this. The number of days between starts seems to affect the start time. D.G. 1C will be started weekly until the cause is identified and corrected. D.G. 1C was returned to service at 0745 on 7/23/80 following the (see attached) METHOD OF DISCOVERY DESCRIPTION (32) (30) OTHER STATUS Performance of surveillance test B (31) 0 0 (29) CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE ESSONNEL EXPOSURES DESCRIPTION (39) 0 0 0 0 30 2 38 SERSONNEL INJURIES DESCRIPTION (41) N/A 0 1 0 (40) OF OR DAVAGE TO FACILITY (43) DESCRIPTIO'. 10 NAC USE ONLY -BLICITY DESCRIPTION (45) 8009020068 N/A (205) 899-5156 W. G. Hairston, III PHONE

NAME OF PREPARER

Cause Description and Corrective Actions - LER 80-044/03L-0 . . . continued successful performance of the surveillance test. Seven timed starts on D.G. 1C since this incident have been performed successfully.