Frorelli





PUBLIC SERVICE INDIANA

S. W. Shields Senior Vice President -Nuclear Division

July 28, 1980

Mr. James G. Keppler, Director U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137 Docket Nos.: STN 50-546 STN 50-547 Construction Permit Nos.: CPPR - 170 CPPR - 171

Marble Hill Nuclear Generating Station - Units 1 and 2

Dear Mr. Keppler:

On April 3, 1979, Mr. C. E. Chmielewski of Public Service Company of Indiana, Inc., (PSI) notified your office of a potentially reportable item as required by 10 CFR 50.55(e). This item involved repair welds on one of the Unit 2 containment sump recirculation piping sleeves which were not re-radiographed after the repair welding was completed.

As planned (see PSI's interim report of May 2, 1979) ultrasonic testing of the subject sleeve welds was performed by Chicago Bridge & Iron to determine their quality. The results of this testing indicated that the welds were not defective and were acceptable as is.

Were this situation to have remained uncorrected it would not have affected adversely the safety of operations of the plant at anytime throughout the expected lifetime of the plant and therefore is not reportable. If you have any questions, please feel free to contact me.

Sincerely,

S. W. Shields

TDG/cg

cc: Director of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

E. R. Schweibinz, P. E.

J. J. Harrison

JUL 3 1 1980