

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | T | N | S | I | N | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 1 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

CONT
01 | REPORT SOURCE | L | 5 | 0 | 5 | 0 | 0 | 0 | 4 | 2 | 7 | 7 | 0 | 1 | 2 | 0 | 8 | 0 | 9 | 0 | 8 | 2 | 7 | 8 | 0 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | Unit 1 was in modes 3, 4, or 5. Failed to perform May 1980 evaluation
03 | for tritium from unit 1 Condenser Vacuum exhaust. There was no danger
04 | to the health and safety of the public. Previous occurrences - none.
05 | On the date this event occurred, the plant had not reached initial
06 | criticality.
07 |
08 |

09 | SYSTEM CODE | Z | Z | 11 | CAUSE CODE | D | 12 | CAUSE SUBCODE | A | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | Z | 14 | COMP SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

17 | LER/RD REPORT NUMBER | 8 | 0 | 21 | EVENT YEAR | 8 | 0 | 22 | SEQUENTIAL REPORT NO | 0 | 9 | 4 | 23 | OCCURRENCE CODE | 0 | 1 | 3 | 24 | REPORT TYPE | L | 25 | REVISION NO | 10 | 26 |
27 | ACTION TAKEN | G | 28 | FUTURE ACTION | Z | 29 | EFFECT ON PLANT | Z | 30 | SHUTDOWN METHOD | Z | 31 | HOURS | 0 | 0 | 0 | 0 | 32 | ATTACHMENT SUBMITTED | N | 33 | NRC-4 FORM 508. | N | 34 | PRIME COMP. SUPPLIER | Z | 35 | COMPONENT MANUFACTURER | Z | 9 | 1 | 9 | 36 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Plant procedure SI-415 did not adequately describe how to take a
11 | monthly sample when the unit is in different modes during the month.
12 | SI-415 has been revised to correct deficiency.
13 |
14 |

15 | FACILITY STATUS | B | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | 31 | DISCOVERY DESCRIPTION | 32 | Review of surveillance instruction
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

16 | ACTIVITY CONTENT RELEASED OF RELEASE | G | 33 | Z | 34 | N/A | 35 | AMOUNT OF ACTIVITY | 36 | LOCATION OF RELEASE | 37 | Condenser vacuum exhaust
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 38 | TYPE | Z | 39 | DESCRIPTION | N/A | 40 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 41 | DESCRIPTION | N/A | 42 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 43 | DESCRIPTION | N/A | 44 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

20 | PUBLICITY ISSUED DESCRIPTION | N/A | 45 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

NAME OF PREPARER: Charles F. Grifley PHONE: 615-842-0295