

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | D | C | C | N | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
 7 8 | 9 | 14 | 15 | 25 | 26 | 30 | 37 CAT 58

CON'T
 0 1 | L | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 8 | 7 | 0 | 7 | 2 | 9 | 8 | 0 | 8 | 0 | 8 | 2 | 9 | 8 | 0 | 9
 7 8 | 60 | 61 | 68 | 69 | 74 | 75 | 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | On July 29, 1980, Engineered Safety Features Actuating System (ESFAS)
 0 3 | channel ZE was deenergized on three occasions with the first occurrence
 0 4 | from 0800 to 0815, the next from 0905 to 0925, and finally from 1025 to 1028
 0 5 | to facilitate corrective maintenance to the Containment Isolation Signal
 0 5 | Bistable as allowed by T.S. 3.3.2.1. The three redundant ESFAS channels
 0 7 | remained operable during the event. This is not a repetitive event.

0 8 | _____ 80

0 9 | SYSTEM CODE: I I B ⑪ | CAUSE CODE: X ⑫ | CAUSE SUBCODE: X ⑬ | COMPONENT CODE: I N S T R U ⑭ | COMP. SUBCODE: I ⑮ | VALVE SUBCODE: Z ⑯

⑰ LER/RO REPORT NUMBER: 8 0 | SEQUENTIAL REPORT NO.: 0 3 6 | OCCURRENCE CODE: 0 3 | REPORT TYPE: L | REVISION NO.: 0

ACTION TAKEN: X ⑰ | FUTURE ACTION: X ⑱ | EFFECT ON PLANT: Z ⑲ | SHUTDOWN METHOD: Z ⑲ | HOURS: 0 0 0 0 ⑳ | ATTACHMENT SUBMITTED: Y ㉓ | NPRD-4 FORM SUB.: Y ㉔ | PRIME COMP. SUPPLIER: A ㉕ | COMPONENT MANUFACTURER: V 1 3 2 ㉖

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ㉗

1 0 | Channel ZE was deenergized while troubleshooting and to replace ZE SIAS
 1 1 | and ZE CIS Bistables. The defective bistables' meter pointers were
 1 2 | oscillating. No cause was found. Efforts to duplicate the symptom
 1 3 | failed. The Vitro Bistables (Model No. 1628-1063) were returned to the
 1 4 | manufacturer for testing/repair.

1 5 | FACILITY STATUS: E ㉘ | % POWER: 1 0 0 0 ㉙ | OTHER STATUS: NA ㉚ | METHOD OF DISCOVERY: A ㉛ | DISCOVERY DESCRIPTION: While taking Log Readings ㉜

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE: Z ㉝ | AMOUNT OF ACTIVITY: NA ㉞ | LOCATION OF RELEASE: NA ㉟

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 0 ㊱ | TYPE: Z ㊲ | DESCRIPTION: NA ㊳

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 0 ㊴ | DESCRIPTION: NA ㊵

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z ㊶ | DESCRIPTION: NA ㊷

2 0 | PUBLICITY ISSUED DESCRIPTION: N ㊸ | DESCRIPTION: NA ㊹

8009030 549

NRC USE ONLY

NAME OF PREPARER: S. M. Davis/P. G. Rizzo | PHONE: (301) 269-4742/4786

LER NO. 80-36/3L
DOCKET NO. 50-318
EVENT DATE 07/29/80
REPORT DATE 08/29/80
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

After replacement of the bistables, applicable sections of the monthly surveillance test were performed satisfactorily. Future action is dependent on the manufacturers' findings. No preventive action is currently planned.