



LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8057 Technical Specification Involved 4.6.G.6  
Reported Under Technical Specification 6.7.2.B.3  
Date of Occurrence 7/30/80 Time of Occurrence N/A Unit 1

Identification and Description of Occurrence:

During past two refueling outages on Unit 1, the testing required by T.S. 4.6.G.6 was overlooked.

Conditions Prior to Occurrence:

Unit 1 @ N/A

Unit 2 @ N/A

Unit 3 @ N/A

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

N/A

Apparent Cause of Occurrence:

Item was not included in the outage work list.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

To be scheduled as a separate surveillance instruction. Inspections will be done at the next refueling outage.

Failure Data:

N/A

\*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

\*Revision: 