



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION III
 799 ROOSEVELT ROAD
 GLEN ELLYN, ILLINOIS 60137

MAY 14 1980

Docket No. 50-358

Cincinnati Gas and Electric
 Company
 ATTN: Mr. Earl A. Borgmann
 Senior Vice President
 Engineering Services
 and Electric Production
 139 East 4th Street
 Cincinnati, OH 45201

Gentlemen:

Enclosed is IE Bulletin No. 80-07, Supplement No. 1, which specifies the NRC offices that should receive written reports submitted in response to this Bulletin.

Should you have any questions regarding this Bulletin or the actions required by you, please contact this office.

Sincerely,

James G. Keppeler
 James G. Keppeler
 Director

Enclosure: IE Bulletin No.
 80-07, Supplement No. 1

cc w/encl:
 Mr. J. R. Schott, Plant
 Superintendent
 Central Files
 Director, NRR/DPM
 Director, NRR/DOR
 PDR
 Local PDR
 NSIC
 TIC
 Harold W. Kohn, Power
 Siting Commission
 Citizens Against a Radioactive
 Environment
 Helen W. Evans, State of Ohio

8009040 531

SSINS No.: 6820
Accession No.:
8005050055

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

May 13, 1980

IE Bulletin No. 80-07
Supplement No. 1

BWR JET PUMP ASSEMBLY FAILURE

C. Reporting Requirements

The information in Items A.3, and B.1, is requested under the provisions of 10 CFR 50.54(f). Accordingly, you are requested to provide within the time periods specified in these items, written statements of this information, signed under oath or affirmation.

These reports should be submitted to the Director of the appropriate NRC Regional Office and a copy should be forwarded to the NRC Office of Inspection and Enforcement, Division of Reactor Operations Inspection, Washington, D.C. 20555.

Approved by GAO, B180225 (R0072); clearance expires 7-31-80. Approval was given under a blanket clearance specifically for identified generic problems.

RECENTLY ISSUED
IE BULLETINS

| Bulletin No. | Subject | Date Issued | Issued To |
|--------------|---|-------------|--|
| 80-13 | Cracking In Core Spray Spargers | 5/12/80 | All BWR's with an OL |
| 80-12 | Decay Heat Removal System Operability | 5/9/80 | Each PWR with an OL |
| 80-11 | Masonry Wall Design | 5/8/80 | All power reactor facilities with an OL, except Trojan |
| 80-10 | Contamination of Nonradioactive System and Resulting Potential for Unmonitored, Uncontrolled Release to Environment | 5/6/80 | All power reactor facilities with an OL or CP |
| 80-09 | Hydramotor Actuator Deficiencies | 4/17/80 | All power reactor operating facilities and holders of power reactor construction permits |
| 80-08 | Examination of Containment Liner Penetration Welds | 4/7/80 | All power reactors with a CP and/or OL no later than April 7, 1980 |
| 80-07 | BWR Jet Pump Assembly Failure | 4/4/80 | All GE BWR-3 and BWR-4 facilities with an OL |
| 80-06 | Engineered Safety Feature (ESF) Reset Controls | 3/13/80 | All power reactor facilities with an OL |
| 80-05 | Vacuum Condition Resulting In Damage To Chemical Volume Control System (CVCS) Holdup Tanks | 3/10/80 | All PWR power reactor facilities holding OLs and to those with a CP |
| 79-01B | Environmental Qualification of Class IE Equipment | 2/29/80 | All power reactor facilities with an OL |
| 80-04 | Analysis of a PWR Main Steam Line Break With Continued Feedwater Addition | 2/8/80 | All PWR reactor facilities holding OLs and to those nearing licensing |