



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76012

bcc to DAC:ADM:  
CENTRAL FILES  
PDR:HQ  
LPDR  
~~TIC~~  
NSIC

May 13, 1980

STATE

Docket No. 50-298


Nebraska Public Power District  
ATTN: J. M. Pilant, Director  
Licensing & Quality Assurance  
Post Office Box 499  
Columbus, Nebraska 68601

Gentlemen:

Enclosed is IE Bulletin No. 80-07, Supplement No. 1, which specifies the NRC offices that should receive written reports submitted in response to this Bulletin.

Should you have any questions regarding this Bulletin or the actions required by you, please contact this office.

Sincerely,

  
K. V. Seyfrit  
Director

Enclosures:

1. IE Bulletin No. 80-07,  
Supplement No. 1
2. List of IE Bulletins  
Recently Issued

cc: L. C. Lessor, Superintendent  
Cooper Nuclear Station  
Post Office Box 98  
Brownville, Nebraska 68321

8009090 046

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

SSINS No.: 6820  
Accession No.:  
8005050055

DUPLICATE

IE Bulletin No. 80-07,  
Supplement No. 1  
Date: May 13, 1980  
Page 1 of 1

BWR JET PUMP ASSEMBLY FAILURE

C. Reporting Requirements

The information in Items A.3, and B.1, is requested under the provisions of 10 CFR 50.54(f). Accordingly, you are requested to provide within the time periods specified in these items, written statements of this information, signed under oath or affirmation.

These reports should be submitted to the Director of the appropriate NRC Regional Office and a copy should be forwarded to the NRC Office of Inspection and Enforcement, Division of Reactor Operations Inspection, Washington, D.C. 20555.

Approved by GAO, B180225 (R0072); clearance expires 7-31-80. Approval was given under a blanket clearance specifically for identified generic problems.

RECENTLY ISSUED IE BULLETINS

| Bulletin No. | Subject   | Date Issued | Issued To  |
|--------------|---|-------------|--|
| 80-07        | BWR Jet Pump Assembly Failure   | 4/4/80      | All GE BWR-3 and BWR-4 facilities with an Operating License (OL)                               |
| 80-08        | Examination of Containment Liner Penetration Welds  | 4/7/80      | All power reactors with a Construction Permit and/or Operating License (OL)                    |
| 80-09        | Hydramotor Actuator Deficiencies  | 4/17/80     | All power reactor operating facilities and holders of power reactor construction permits (CPs) |
| 80-10        | Contamination of Nonradioactive System and Resulting Potential for Unmonitored, Uncontrolled Release to Environment | 5/6/80      | All power reactor facilities with an Operating License (OL) or Construction Permit (CP)        |
| 80-11        | Masonry Wall Design   | 5/8/80      | All power reactor facilities with an Operating License (OL), except Trojan,                    |
| 80-12        | Decay Heat Removal System Operability   | 5/9/80      | Each PWR with an Operating License (OL)  |
| 80-13        | Cracking In Core Spray  | 5/12/80     | All BWR's with an Operating License (OL)   |