



Portland General Electric Company

September 5, 1980

Trojan Nuclear Plant  
Docket 50-344  
License NPF-1

Director of Nuclear Reactor Regulation  
ATTN: Mr. Robert A. Clark, Chief  
Operating Reactors Branch No. 3  
Division of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Sir:

Attached for your information as Attachment 1 is Licensee Event Report 80-17 concerning an occurrence where a piece of redundant safety-related equipment was rendered inoperable as a result of a concrete core drilling operation. This work was not part of the Trojan Control Building Modification Program authorized by condition 2.C.(12) of Operating License NPF-1 (Amendment 47, July 25, 1980), and thus was not subject to the conditions and commitments associated with that program.

As discussed in Attachment 2, we have evaluated the implications of this occurrence relative to the extensive core drilling involved in the Trojan Control Building Modification Program. We have concluded that the precautions, methods and controls required under the conditions and commitments applicable to the Control Building Modification Program provide assurance that a similar occurrence will not occur during core drilling performed for that program.

Sincerely,

c: Mr. Lynn Frank, Director  
State of Oregon  
Department of Energy

Mr. R. H. Engelken, Director  
U. S. Nuclear Regulatory Commission  
Region V

Control Building Service List

8009100 449

5

A002  
S, 11