



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76012

16 JUL 1980

Docket No. 99900259/80-01


Combustion Engineering, Incorporated  
C-E Avery Division  
Attn: Mr. P. F. Avery, Jr.  
General Manager  
Old Dover Road, P. O. Box 630  
Newington, NH 03801

Gentlemen:

Thank you for your letter of July 3, 1980, in response to our letter dated June 6, 1980. As a result of our review, we find that additional information, as discussed with your Ms. D. C. Almeda during a telephone call on July 15, 1980, is needed. Specifically, for Item E, you state that the applicable DWP, RP-10-2 has been corrected to document the complete repair. However, that DWP is associated with the repair performed on the ferritic base material only. You did not address the missing DWP, WMC-10-11, which should have been used to identify the material used for the initial Inconel cladding layer. In addition, please provide us with the documented basis for making the determination that the electrodes used for the first layer of the repair was also used for the balance. This may also be applicable to your response regarding the initial Inconel cladding layer.

Please provide this additional information within twenty (20) days in order that we may complete our review in a timely manner.

Sincerely,

  
Uldis Potapovs, Chief  
Vendor Inspection Branch

0200616008