

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | T | N | S | N | P | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 1 | 3 | 2 | 1 | 7 | 7 | 0 | 8 | 2 | 9 | 1 | 8 | 1 | 0 | 3 | 0 | 9 | 1 | 1 | 1 | 8 | 0 | 3

02 | On August 29, 1980, while in mode 5, a pinhole leak was discovered in
03 | the rod travel housing-latch housing interface seal weld on CRDM C-11.
04 | There was no effect upon public health or safety. Previous
05 | occurrences: none.

09 | C | A | 11 | B | 12 | B | 13 | C | P | D | R | I | V | E | 14 | Z | 15 | Z | 16
17 | 8 | 10 | 14 | 1 | 0 | 1 | T | 0
18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 22 | N | 24 | N | 25 | W | 1 | 2 | 1 | 0 | 26

10 | The fault will be ground out and weld repaired.
11 |
12 |
13 |
14 |

15 | G | 28 | 0 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Operator observation | 32
16 | Z | 33 | Z | 34 | NA | 35 | NA | 36
17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
18 | 0 | 0 | 0 | 40 | NA | 41
19 | Z | 47 | NA | 43
20 | N | 51 | NA | 45

NAME OF PREPARER: D. O. Williams PHONE: 615-842-6967

POOR ORIGINAL

8009190511