8	~	1-	60	-0	32
61	1-	6	~~		52

USNRC REGION I

.,

DO SEPTS PIZ: 10

ACILITY Grand Gulf 1		DOCKET NO. 50-416
ATE 9/12/80	TIME_3:30 p.m.	LIC. OCC. NO
UBJECT: CDR - RCI PIP	pe Support Deficiencies	
· · · · · · · · · · · · · · · · · · ·		
ESCRIPTION OF OCCURREN	CE:	
	ac. (RCI) reported to MP&L's A	
were not fabricated	and installed in accordance	with specifications. These
	cated on site. The following	
	ted for steel angle, hangers w	the second se
but the fouthside e	xtended beyond the imbed, seve	eral pipe clamps broken away
	and hangers omitted. Correctiv	
	tigation. Report due 10/13/80	
	,	
		SIGNATURE M. D. Hunt

B019 50/1

OFFICIAL COPY

8009260648

5