



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

TIC

August 27, 1980



Mr. R. H. Engelken, Director
Region V, Office of Inspection
and Enforcement
U.S. Nuclear Regulatory Commission
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, CA 94596

Docket 50-312
Rancho Seco Nuclear Generating
Station, Unit 1
IE Bulletin 80-19 Revision 1 Response

Dear Mr. Engelken:

Rancho Seco does have mercury wetted relays installed within the Reactor Protection System logic matrix, however, the relays are not C.P. Clare Model HG2X-1011.

The relays used at Rancho Seco are HGS2MT-5105, CH5TN-1007, HGSM-5011, and CH5TN-1005. Therefore, this response is submitted as a negative declaration to IE Bulletin 80-19 Revision 1.

The time expended in conduct of this review is approximately eight (8) hours.

Sincerely,

Wm. C. Walbridge
Wm. C. Walbridge
General Manager

cc: Director, Division of Reactor Operations Inspection
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8010230184

Q