

Appendix A

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-237

Based on the inspection conducted on September 20-22, 1977, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. The item below is a deficiency.

Contrary to Technical Specifications 6.2.A.2, the licensee failed to adhere to an approved refueling operations procedure, DFP 800-1, during September, 1977, in that personnel on the refueling floor work area had loose objects in their pockets and did not tape monitoring badges and pencils in place.

8009120 722