-	LICENSEE EVENT REPORT
	CONTROL BLOCK: [ ]
0 1	I L Z I S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 6 57 CAT 58 5
CCN'T 0 1 7 8	REPORT L 6 0 5 0 0 0 0 2 9 5 7 9 8 2 0 8 0 9 1 1 8 0 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10    During normal operation it was determined that the operability surveil-
	lance for the Pyra-Alarm Detectors could not be performed in the pre-
0 3	scribed interval as specified in T.S. 4.21.1. Since the detectors were
0 4	, still able to perform their function there was no affect on the health
0 5	
0 6	and safety of the public.
0 7	
08	9
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	THE ROLL EVENT YEAR REPORT NO.    Seport   Seport   Seport No.   Sepor
10	Because the supplier of test das shipped the incorrect item as well as
111	the large increase in the number of cetectors there was an insufficient
12	amount of test gas on-site to test the PYRA-ALARMS. The storeroom low
1 3	limit has been increased to prevent recurrence.
114	
7 8	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
	A DANIEL CONTENT
	RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
. [1]7]	NUMBER TYPE DESCRIPTION (30) 1 0 0 0 (37) Z (38) NA
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION (1)
1 8.	OOOO NA OFFICE NA OFFICE NA OFFICE NA SO
19	LOSS OF ON DAMAGE TO FACILITY (4)  TYPE DESCRIPTION  NA  NA  NA
20	
	NAME OF PHEPARER E. J. Fuerst PHONE: 312-746-2084 Ext 216 %