LICENSEE EVENT REPORT

CONTROL BLOCK:
0 1 I Z I S 2 2 0 0 - 0 0 0 0 - 0 0
CON'T SOURCE L G O S O O O O O O O O
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) 1 During normal operation at 1630 hours 2D MSIV low pressure annunciator
[0]3 alarmed and oil pump would not run. The MSIV was declared inoperable and
[0]4] [unit shutdown commenced. At 1849 hours the problem was determined to be
0 5 a failed control power transformer. The transformer was replaced and the
ole oil pump started. The MSIV was declared operable and unit shutdown ter-
old minated. At no time did oil pressure decay to the point where the valve
would fail to close. The health and safety of the public was not affected
SYSTEM CAUSE CODE SUBCODE SUBC
LERRO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT NO. 17 REPORT 8 0 0 0 3 L 0 3 L 0 0
ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORMSUB. SUPPLIER MANUFACTURER
A 18 Z 19 B 20 Z 21 0 0 0 0 0 N 30 Y 24 X 35 G 0 8 0 6
The cause of this event was a failed control power transformer which
[1] [would not allow the oil to run. The transformer was replaced and the
MSIV returned to an operating condition. This type of event has not
[1]3 occurred in the past. No further action is required.
TI4 L
PACILITY STATUS OF DISCOVERY DESCRIPTION 32 1 5 E 38 0 8 8 39 NA A 31 Operator Observation 10 12 13 14 45 46 46 46 46 46 46 4
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 NA NA NA NA NA NA NA NA NA N
NUMBER TYPE DESCRIPTION (39) NA NA
PERSONNEL INJURIES NUMBER DESCRIPTION (1) NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA NA
PUBLICITY NA 8009230704 NRC USE ONLY
NAME OF PURPARED T. A. Printz PHONE, 312-746-2084 0