



Wisconsin Electric POWER COMPANY
231 WEST MICHIGAN, MILWAUKEE, WISCONSIN 53201

September 26, 1980

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-301
LICENSEE EVENT REPORT NO. 80-008/01T-0
POINT BEACH NUCLEAR PLANT UNIT 2

Enclosed is Licensee Event Report No. 80-008/01T-0 (a 14-day follow-up report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.9, "Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than that assumed in the accident analyses, in the safety analysis report, or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition".

Very truly yours,

C. W. Fay, Director
Nuclear Power Department

Enclosure

Copies to C. F. Riederer - PSCW
NRC Resident Inspector

A002
3
1/1

8010070 561

S

SEP 30 1980